

Alex-Tronix Service Bulletin No. 17, Rev 1, as of 3-26-2008

Controllers: Enercon 4-24, and Enercon Plus.... (not ECN 4/8)

Issue: Software Fixes for Larger Enercon Pedestal Controller.

See if you need to upgrade the software in your ECN irrigation controller.

Good Morning Alex-Tronix Customers...Today we make sure your ECN controller's software is up to date. You will need to note the **model number** ("Plus" version or not) and **firmware version** on your ECN controller. To do this, wake up the controller by pressing down any button on the keypad until the display illuminates, then turn the function selector knob on **HELP**. Write down the software version on the display.

There are two versions of the Enercon -- One with temperature budgeting (plus), and one without -- (4-24). If the software version is not one of the following, then you should contact the factory to make arrangements to send it in and have it upgraded. This procedure takes a few minutes to do, and there is no charge. The current software versions as per the date of this bulletin are:

ENERCON 4-24: SOFTWARE: V. 1.19

ENERCON PLUS: SOFTWARE: V. 4.01

Questions??? Comments? Gripes? Tech Support: Aram Tokatian 888-224-7630 ext 16.

